



The Safe Choice

HYSTER SALES TIPS

Correction to the E45-70XN MMST

This is a quick note to advise you of a clarification to the MMST on the E45-70XN trucks.

In the Serviceability section where it talks about the Traction motor, it says that the Class H insulation is rated at 180 degrees. This is correct. However, the 180 degree is Celsius. This converts to 356 degrees Fahrenheit. Obviously this is a huge difference when you are talking to your customers.

One of the nice things about having the MMST set up with the various PowerPoint presentations is that you can fix this on the slide. Go to the folder where you have saved all the MMST files. Open the PowerPoint presentation on Serviceability. Go to the slide on the traction motor. You can click on the 180 number and change it to 356. Then also add F after the degree symbol to clarify that this temperature is Fahrenheit. Then save the file. Now when you run the MMST your fix will be there.

If you have any questions on this, please contact Glenn Spiers or Bob Houston and we can help you with this.